

Environmental Impact
Statement
for the
Salem to Manchester
Corridor

Freeway Level of Service

Node	LOS
MA State Line to Exit 1	Е
Exit 1 to Exit 2	Е
Exit 2 to Exit 3	Е
Exit 3 to Exit 4	D

Ramp Junction Level of Service


	Node	LOS	
		AM	PM
	1A	Α	С
	1B	В	F
	1C	F	D
	1D	F	D
	2A	В	F
	2B	В	F
	2C/2D (weave)	F	D
	3A	В	F
	3B	В	D
	3C	Е	С
	3D	F	С

Signalized Intersection Level of Service

Node	LOS	
	AM	PM
1	В	В
2	С	D
3	E	F
4	С	E
5	В	С
7	В	F*
8	В	В

Unsignalized Intersection Level of Service

Node	Node LC	
Node	AM	PM
6	С	F



Vanasse Hangen Brustlin, Inc.

Figure 3.2-3 Level of Service Summary 1997 Existing Conditions Sheet 1 of 2

calculated for AM and PM peak hour volumes.